



Fulford
CERTIFICATION

Marine Pedestal Mount Crane Operator Training

Site Requirements

All of Fulford Certification's training programs are delivered on your worksite. The following site requirements are needed for us to deliver our courses.

Meeting Room

A meeting room with sufficient space for the course participants and the instructor is required for the delivery of the theory section of the course. A lunch room or similar space can be used but must be closed to staff not taking the training.

Work Area with Marine Pedestal Mount Crane

The hands-on section of the training requires access to a work area (vessel deck, dock, barge, etc) and use of a pedestal mount crane to hoist and move loads for the entire afternoon. The crane must be in good working order, have a valid safety inspection, logbook and operators manual.

Objects for Lifting & Rigging

Three or more loads (ideally of different shapes and weights) on site. Minimum 300 lbs but no more than 50% of the crane's capacity. Rigging to be used must be in good condition and hoisting chains must have an up-to-date annual inspection document tag.